

# KLW-P1

<http://www.gigahertz-optik.de/de-de/produkt/KLW-P1>

Produkt-Tags: VIS

**E<sub>v</sub>**

# Überblick

Illuminance of light sources is measured with an illuminance detector and an Optometer. The illuminance detector is calibrated in reference to an illuminance standard source. The optometer is calibrated in reference to a DAkkS calibrated current source.

A factory calibration certificate is supplied listing the light source data, measurement set-up, traceability and calibration uncertainty.

## Bestellinformationen

Artikel-Nr	Modell	Beschreibung
Kalibrierung		
	KLW-P1-01	Illuminance calibration of light sources. Factory calibration certificate.
	KLW-P1-RP	Set-up charge for non-Gigahertz-Optik sources